

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

BI309  
SE  
1/4-1/2  
0.471 mi.  
2486 ft.

NY AQUARIUM - TTF  
502 SURF AVE  
BROOKLYN, NY  
Site 3 of 3 in cluster BI

NY LTANKS S106124057  
N/A

Relative:  
Higher

Actual:  
4 ft.

LTANKS:

Name: CONEY ISLAND AQUARIUM  
Address: 502 SURF AVE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0312016 / 2004-02-11  
Facility ID: 0312016  
Site ID: 177643  
Spill Date: 2004-01-27  
Spill Cause: Tank Overfill  
Spill Source: Unknown  
Spill Class: C4  
Cleanup Ceased: Not reported  
SWIS: 2401  
Investigator: JMKRIMGO  
Referred To: Not reported  
Reported to Dept: 2004-01-27  
CID: 444  
Water Affected: Not reported  
Spill Notifier: Other  
Last Inspection: Not reported  
Recommended Penalty: False  
  
Meets Standard: False  
UST Involvement: False  
Remediation Phase: 0  
Date Entered In Computer: 2004-01-27  
Spill Record Last Update: 2004-02-10  
Spiller Name: MIKE  
Spiller Company: BRIDGE TRANSPORTATION  
Spiller Address: Not reported  
Spiller County: 001  
Spiller Contact: UNKNOWN  
Spiller Phone: Not reported  
Spiller Extention: Not reported  
DEC Region: 2  
DER Facility ID: 149265  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was  
KRIMGOLD Sangesland spoke to Ray Lara Spill of 20 gallons on walkway  
- all cement 30' x 7' all outside on ice. Ray says the spill is all  
contained and they have already collected all of the speedie dry into  
drums. Aquarium manager is concerned that the job may not be  
complete. Site visit is suggested. 1/28/04. J. Krimgold was unable to  
visit site due to a heavy snow storm. NFA."

Remarks: "CALLER WAS CALLED IN TO CLEAN UP: "

All Materials:

Site ID: 177643  
Operable Unit ID: 879532  
Operable Unit: 01  
Material ID: 497251  
Material Code: 0001A  
Material Name: #2 fuel oil  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 20.00

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Units: G  
Recovered: .00  
Oxygenate: Not reported

Name: NY AQUARIUM - TTF  
Address: 502 SURF AVE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 1104700 / 2011-12-22  
Facility ID: 1104700  
Site ID: 452311  
Spill Date: 2011-07-25  
Spill Cause: Tank Test Failure  
Spill Source: Gasoline Station or other PBS Facility  
Spill Class: C4  
Cleanup Ceased: Not reported  
SWIS: 2401  
Investigator: smsanges  
Referred To: Not reported  
Reported to Dept: 2011-07-25  
CID: Not reported  
Water Affected: Not reported  
Spill Notifier: Other  
Last Inspection: Not reported  
Recommended Penalty: False

Meets Standard: False  
UST Involvement: False  
Remediation Phase: 0  
Date Entered In Computer: 2011-07-25  
Spill Record Last Update: 2011-12-22  
Spiller Name: KEN  
Spiller Company: UNKNOWN  
Spiller Address: 502 SURF AVE  
Spiller County: 999  
Spiller Contact: KEN  
Spiller Phone: Not reported  
Spiller Extention: Not reported  
DEC Region: 2  
DER Facility ID: 149265  
DEC Memo:

"10/28/2011 Eastern Environmental called to get info on the site. They are bidding on the work for the NY Aquarium. Plan is to either remove or abandon the tank soon . When/if they get the job, Eastern will call back with more details. 11/28/11 Tues drain tank, Wed borings around tank, Thurs borings through tank, if all clean then fill with sand and close out. 12/22/2011 Sangesland reviews report from Eastern Environmental dated 12/14/2011: Report outlines that the tank was drained, cleaned, inspected & found to be in good condition. No signs of the tank leaking (TTF probably came from loose lines). Tank was cleaned and then filled with sand/gravel/cement slurry. Borings were taken around the tank (all clean). No contaminated soil was found. Spill Closed."

Remarks: "NY AQUARIUM"

All Materials:

Site ID: 452311  
Operable Unit ID: 1202489  
Operable Unit: 01  
Material ID: 2199075  
Material Code: 0001A  
Material Name: #2 fuel oil

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported